Hurn Road - 1st Jct A338, Blackwate..(H)

6 Months - PLANNED

Tree Number Common name Height Trunk Age Class Condition Recommendations

Sgl/1 (220184) Oak Species 11.0m 108cm Semi-mature Single Stemmed Crown clean

Dieback - Crown Remove all deadwood Ivy/climbing plants NOT Ivy band @ base

SIGNIFICANT Crown lift to 2.3 m over Footpath Major Deadwood - Crown lift to 5.2m over Highway BRANCHES/STEMS

Date: 18/10/2012age 1

Sub-total: 1 trees

Total: 1 trees

Hurn Road - Hillside Drive To St Ca..(H)

ESSENTIAL WORKS YR 1

Tree Number Common name Height Trunk Age Class Condition Recommendations

Sgl/20 (220372 Scot's pine 9.0m 25cm Young Co-dominant Stems Fell to ground level

Tight Forks/Included Bark-MAIN

FÖRK Minor

Deadwood-BRANCHES/STEMS

Sgl/44 (220504 Monterey pine 9.0m 40cm Semi-mature Lean > than 20% Fell to ground level

Single Stemmed Major Deadwood -BRANCHES/STEMS

Minor

Deadwood-BRANCHES/STEMS

Sub-total: 2 trees

6 Months - PLANNED

Tree Number Common name Height Trunk Age Class Condition Recommendations

Hurn Road - Hillside Drive To St Ca..(H) ...(contd)...

Tree Number	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/13 (220344	Monterey pine	10.0m	40cm	Semi-mature	Single Stemmed Minor Deadwood-BRANCHES/STEMS	Fell to ground level
Sgl/41 (220492	Monterey pine	9.0m	40cm	Semi-mature	Single Stemmed Minor Deadwood-BRANCHES/STEMS	Crown lift to 5.2m over Highway
Sgl/45 (220508	Scot's pine	9.0m	25cm	Young	Single Stemmed Co-dominant Stems Minor Deadwood-BRANCHES/STEMS	Fell to ground level
Sgl/99 (227124	Scot's pine	13.Om	37cm	Semi-mature	Single Stemmed I vy/climbers Restricting I nspection I vy/climbing Plants I nfesting Crown Major Deadwood - BRANCHES/STEMS	Remove major deadwood I vy band @ base and remove ivy
Sgl/100 (227128	Scot's pine	11.Om	38cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS Low Pendulous Major Branching	Remove major deadwood Crown lift to 2.3 m over Footpath - remove 3x large limbs Crown lift to 5.2m over Highway
Sgl/101 (227132	Scot's pine	10.0m	35cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS Low Pendulous Major Branching	Remove major deadwood Crown lift to 5.2m over Highway

Hurn Road - Hillside Drive To St Ca..(H) ...(contd).. 6 Months - PLANNED ...(contd).. Condition Tree Number Common name Height Trunk Age Class Recommendations SgI/103 (22714(Scot's pine Single Stemmed Remove major deadwood 13.0m 40cm Semi-mature Lvy/climbers Restricting Ivy band @ base and remove ivy Inspection Lvy/climbing Plants Infesting Crown Major Deadwood -BRANCHES/STEMS SgI/104 (227144 Rowan Fell to ground level 5.0m 13cm Semi-mature Dying Grind Stump & reinstate Multi-Stemmed Plant replacement tree (227148 Scot's pine Single Stemmed Remove major deadwood Sql/105 9.0m 29cm Young Crown lift to 2.3 m over Footpath Major Deadwood -**BRANCHES/STEMS** Crown lift to 5.2m over Highway (227152 Scot's pine 9.0m 29cm Young Single Stemmed Remove major deadwood Sql/106 Major Deadwood -Crown lift to 2.3 m over Footpath BRANCHES/STEMS Crown lift to 5.2m over Highway Sub-total: 10 trees 28 days -MED TERM 2b

Tree N	umber	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/7	(220320	Monterey pine	10.0m	40cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Crown lift to 5.2m over Highway
Sgl/8	(220324	Scot's pine	9.0m	35cm	Semi-mature	Single Stemmed Minor Deadwood-BRANCHES/STEMS	Crown lift to 5.2m over Highway

Hurn Road - Hillside Drive To St Ca..(H) ...(contd)...

28 days -MED TERM 2b ...(contd)...

,		` ,					
Tree Nu	mber	Common name	Height	Trunk	Age Class	Condition	Recommendations
SgI/9	(220328	Monterey pine	9.0m	36cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS Minor Deadwood-BRANCHES/STEMS	Fell to ground level
SgI/10	(220332	Monterey pine	8.0m	40cm	Early Mature	Single Stemmed I vy/climbing plants NOT SI GNI FI CANT Minor Deadwood-BRANCHES/STEMS	Fell to ground level
SgI/11	(220336	Scot's pine	6.0m	20cm	Young	Single Stemmed Minor Deadwood-BRANCHES/STEMS	Fell to ground level
Sgl/16	(220356	Monterey pine	9.0m	35cm	Semi-mature	Single Stemmed Minor Deadwood-BRANCHES/STEMS	Fell to ground level
SgI/18	(220364	Monterey pine	9.0m	40cm	Semi-mature	Single Stemmed I vy/climbing plants NOT SI GNI FI CANT Major Deadwood - BRANCHES/STEMS Minor Deadwood-BRANCHES/STEMS	Fell to ground level
SgI/23	(220384	English Oak	13.0m	51cm	Semi-mature	Single Stemmed Minor Deadwood-BRANCHES/STEMS	Remove major deadwood Crown lift to 5.2m over Highway
SgI/24	(220388	Monterey pine	10.0m	50cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS Minor Deadwood-BRANCHES/STEMS	Crown lift to 5.2m over Highway

Hurn Road - Hillside Drive To St Ca..(H) ...(contd)...

28 days -MED TERM 2b ...(contd)...

Tree Number	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/29 (22044(English Oak	11.Om	44cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS Minor Deadwood-BRANCHES/STEMS	Remove epicormics - trunk/crown Remove major deadwood Crown lift to 5.2m over Highway
Sgl/51 (220442	English Oak	16.0m	95cm	Mature	Single Stemmed I vy/climbing Plants I nfesting Crown Minor Deadwood-BRANCHES/STEMS	Remove major deadwood Ivy band @ base Crown lift to 5.2m over Highway
Sgl/30 (22044 ²	English Oak	13.0m	45cm	Semi-mature	Single Stemmed Regrown pollard or topped tree Minor Deadwood-BRANCHES/STEMS	Remove epicormics - trunk/crown
SgI/31 (220448	Monterey pine	11.Om	60cm	Semi-mature	Single Stemmed Lvy/climbing plants NOT SIGNIFICANT Major Deadwood - BRANCHES/STEMS Minor Deadwood-BRANCHES/STEMS	Fell to ground level
Sgl/32 (220452	Scot's pine	10.0m	45cm	Semi-mature	Multi-Stemmed Ivy/climbing plants NOT SIGNIFICANT Minor Deadwood-BRANCHES/STEMS	I vy band @ base Crown lift to 5.2m over Highway
Sgl/35 (22045€	Scot's pine	8.0m	35cm	Mature	Multi-Stemmed Ivy/climbing plants NOT SIGNIFICANT Minor Deadwood-BRANCHES/STEMS	Fell to ground level

Hurn Road - Hillside Drive To St Ca..(H) ...(contd)..

28 days -MED TERM 2b ...(contd)...

Tree Number	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/36 (220460	Cypress	9.0m	35cm	Young	Multi-Stemmed I vy/climbing plants NOT SI GNI FI CANT Minor Deadwood-BRANCHES/STEMS	Fell to ground level
Sgl/34 (22046 ²	Cypress	9.0m	35cm	Mature	Multi-Stemmed Lvy/climbing plants NOT SIGNIFICANT Minor Deadwood-BRANCHES/STEMS	Fell to ground level
SgI/52 (220468	Cypress	9.0m	29cm	Semi-mature	Multi-Stemmed Lvy/climbing plants NOT SIGNIFICANT Minor Deadwood-BRANCHES/STEMS	Fell to ground level
Sgl/33 (220472	Cypress	8.0m	35cm	Semi-mature	Multi-Stemmed Ivy/climbing plants NOT SIGNIFICANT Minor Deadwood-BRANCHES/STEMS	Fell to ground level
Sgl/37 (220476	Scot's pine	8.0m	35cm	Semi-mature	Multi-Stemmed Ivy/climbing plants NOT SIGNIFICANT Minor Deadwood-BRANCHES/STEMS	Fell to ground level
Sgl/39 (22048 ²	English Oak	15.0m	93cm	Semi-mature	Single Stemmed Minor Deadwood-BRANCHES/STEMS	Remove major deadwood Crown lift to 5.2m over Highway Reduce o/extended branches - by 2-3m large limb @4 over service road. reduce any limbs left exposed by reduction of limb

Hurn Road - Hillside Drive To St Ca..(H) ...(contd)...

28 days -MED TERM 2b ...(contd)..

Tree Nu	mber	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/40	(220488	English Oak	14.0m	50cm	Semi-mature	Single Stemmed Minor Deadwood-BRANCHES/STEMS	Ivy band @ base Crown lift to 5.2m over Highway
SgI/42	(220496	Cypress	4.0m	15cm	Young	Single Stemmed	Fell to ground level
Sgl/43	(220500	Cypress	4.0m	15cm	Young	Single Stemmed	Fell to ground level
Sgl/46	(220512	Monterey pine	9.0m	40cm	Early Mature	Single Stemmed I vy/climbing plants NOT SI GNI FI CANT Major Deadwood - BRANCHES/STEMS Minor Deadwood-BRANCHES/STEMS	Fell to ground level
Sgl/50	(220528	Silver Birch	9.0m	25cm	Mature	Single Stemmed Regrown pollard or topped tree	Crown lift to 2.3 m over Footpath

Sub-total: 26 trees

> 38 trees Total:

Hurn Road - St Catherine's Way R/a ..(H)

6 Months - PLANNED

Tree Nu	umber	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/1	(226000)	Oak Species	13.0m	41cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove major deadwood Crown lift to 5.2m over Highway

Hurn Road - St Catherine's Way R/a ..(H) ...(contd)..

		, ,					
Tree Nu	mber	Common name	Height	Trunk	Age Class	Condition	Recommendations
SgI/2	(226004	Oak Species	12.0m	32cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove epicormics - trunk/crown Remove major deadwood O/HEAD CABLES MAY REQ SHUTDOWN
SgI/3	(226008	Oak Species	8.0m	38cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS Suppressed	Remove major deadwood Crown lift to 5.2m over Highway
SgI/4	(226012)	Oak Species	8.0m	30cm	Semi-mature	Single Stemmed Minor Deadwood-BRANCHES/STEMS Suppressed	Remove epicormics - trunk/crown O/HEAD CABLES MAY REQ SHUTDOWN
SgI/5	(226016)	Oak Species	12.0m	45cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove major deadwood Crown lift to 5.2m over Highway
SgI/6	(226020	Oak Species	9.0m	30cm	Semi-mature	Multi-Stemmed Co-dominant Stems Minor Deadwood-BRANCHES/STEMS	Crown lift to 5.2m over Highway
SgI/7	(226024	Oak Species	11.0m	50cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove major deadwood Crown lift to 5.2m over Highway
SgI/8	(226028	Oak Species	11.Om	37cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove major deadwood Crown lift to 5.2m over Highway

Hurn Road - St Catherine's Way R/a ..(H) ...(contd)...

0 11.011		(66					
Tree N	Number	Common name	Height	Trunk	Age Class	Condition	Recommendations
SgI/9	(226136)	Scot's pine	12.0m	35cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS Splits/Cracks - MAI N BRANCHES/STEMS - split limb over private property	Remove defective branches - split limb Remove major deadwood I vy band @ base
SgI/10	(226140	Scot's pine	12.0m	38cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS Low Pendulous Major Branching Over Extended Major Branching	Remove major deadwood Crown lift to 5.2m over Highway Reduce o/extended branches - limbs over private property
Sgl/13	(226152	Silver Birch	13.0m	35cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove major deadwood Crown Reduction by - 2-3m O/HEAD CABLES MAY REQ SHUTDOWN
SgI/15	(226160	Silver Birch	14.0m	35cm	Mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove major deadwood Crown Reduction by - 2-3m O/HEAD CABLES MAY REQ SHUTDOWN
SgI/16	(226728	English Oak	11.Om	42cm	Semi-mature	Multi-Stemmed Co-dominant Stems Major Deadwood - BRANCHES/STEMS	Remove major deadwood Crown lift to 5.2m over Highway
SgI/17	(226732	English Oak	10.0m	39cm	Semi-mature	Lean < than 20% Single Stemmed Co-dominant Stems I mbalanced crown Crossing/rubbing MAIN BRANCHES/STEM Major Deadwood - BRANCHES/STEMS Suppressed	Fell to ground level

Date: 18/10/20 13 e 10

Hurn Road - St Catherine's Way R/a ..(H) ...(contd)...

6 Month	ns - PLANI	NED(contd)					
Tree Nu	umber	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/18	(226736	English Oak	10.0m	39cm	Semi-mature	Lean < than 20% Single Stemmed Co-dominant Stems I mbalanced crown Crossing/rubbing MAI N BRANCHES/STEM Major Deadwood - BRANCHES/STEMS Suppressed	Remove major deadwood Crown lift to 5.2m over Highway
Sgl/19	(22674C	Cherry	4.0m	27cm	Semi-mature	Lean < than 20% Single Stemmed Co-dominant Stems Major Deadwood - BRANCHES/STEMS Suppressed Cankers - TRUNK	Fell to ground level
Sgl/21	(226748	English Oak	10.0m	40cm	Semi-mature	Single Stemmed Decline to secondary crown I vy/climbers Restricting I nspection I vy/climbing Plants I nfesting Crown Major Deadwood - BRANCHES/STEMS	Remove major deadwood I vy band @ base
SgI/22	(226752	English Oak	10.0m	42cm	Semi-mature	Single Stemmed Co-dominant Stems Basal suckers I mbalanced crown Major Deadwood - BRANCHES/STEMS Over Extended Major Branching Suppressed	Reduce o/extended branches - reduce lateral branches over service road by up to 4m. reduce lateral branches over main road by up to 3m. leave tree with a more rounded balanced canopy

Tree work - Hurn Road Xchurch - 2013 - Highways - General Tree Report Date: 18/10/20Plage 11

Hurn Road - St Catherine's Way R/a ..(H) ...(contd)...

O MONTHS - I LAN	INLD(conta)					
Tree Number	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/23 (226756	Sycamore	11.Om	39cm	Semi-mature	Single Stemmed Co-dominant Stems I vy/climbers Restricting I nspection Major Deadwood - BRANCHES/STEMS	Remove major deadwood I vy band @ base Crown lift to 5.2m over Highway Prune to clear lamp column
Sgl/24 (226760	Sycamore	11.Om	39cm	Semi-mature	Single Stemmed Co-dominant Stems Tight Forks/Included Bark-MAIN FORK Weak Attachment Points- FORK(S) I vy/climbers Restricting I nspection Crossing/rubbing MAIN BRANCHES/STEM Major Deadwood - BRANCHES/STEMS	Further inspection required I vy band @ base I Crown lift to 5.2m over Highway
Sgl/25 (22676 ²	English Oak	12.0m	44cm	Semi-mature	Single Stemmed Co-dominant Stems Major Deadwood - BRANCHES/STEMS	Remove epicormics - trunk/crown Remove major deadwood Crown lift to 5.2m over Highway
Sgl/26 (226768	English Oak	14.0m	47cm	Semi-mature	Single Stemmed Co-dominant Stems Major Deadwood - BRANCHES/STEMS	Remove epicormics - trunk/crown Remove major deadwood Crown lift to 5.2m over Highway
Sgl/27 (226772	English Oak	11.Om	38cm	Semi-mature	Single Stemmed Decline to secondary crown Major Deadwood - BRANCHES/STEMS	Remove epicormics - trunk/crown Remove major deadwood Crown lift to 5.2m over Highway Crown Reduction by - up to 2m

Hurn Road - St Catherine's Way R/a ..(H) ...(contd)...

	Tree Nur	mber	Common name	Height	Trunk	Age Class	Condition	Recommendations
:	SgI/28	(226776	English Oak	12.0m	40cm	Semi-mature	Lean < than 20% Single Stemmed Tight Forks/Included Bark-MAIN FORK Imbalanced crown Major Deadwood - BRANCHES/STEMS Suppressed	Remove epicormics - trunk/crown Remove major deadwood Formative and corrective pruning - reduce main stem towards main road by up to 3-4m to encourage more evenly grown canopy Crown lift to 5.2m over Highway
	Sgl/29	(226780	English Oak	12.0m	45cm	Semi-mature	Multi-Stemmed Co-dominant Stems Major Deadwood - BRANCHES/STEMS	Remove epicormics - trunk/crown Remove major deadwood Crown lift to 5.2m over Highway
:	SgI/30	(226784	English Oak	12.0m	48cm	Semi-mature	Single Stemmed Co-dominant Stems Decline to secondary crown Major Deadwood - BRANCHES/STEMS	Remove epicormics - trunk/crown Remove major deadwood Crown lift to 5.2m over Highway
	SgI/31	(226788	English Oak	11.Om	46cm	Semi-mature	Single Stemmed Co-dominant Stems Lvy/climbers Restricting Inspection Major Deadwood - BRANCHES/STEMS Suppressed	Remove epicormics - trunk/crown Remove major deadwood I vy band @ base Crown lift to 5.2m over Highway
	SgI/32	(226792	English Oak	15.0m	75cm	Semi-mature	Single Stemmed Co-dominant Stems Ivy/climbers Restricting Inspection Major Deadwood - BRANCHES/STEMS	Remove epicormics - trunk/crown Remove major deadwood I vy band @ base Crown lift to 5.2m over Highway
	Sgl/34	(22685€	Cherry	5.0m	27cm	Young	Single Stemmed Co-dominant Stems	Crown lift to 5.2m over Highway

Hurn Road - St Catherine's Way R/a ..(H) ...(contd)..

Tree Nu	mber	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/36	(226864	English Oak	5.0m	22cm	Young	Single Stemmed	Crown lift to 5.2m over Highway
Sgl/37	(226868	English Oak	6.0m	25cm	Young	Single Stemmed Co-dominant Stems	Formative and corrective pruning - reduce co-dominent stem by 1-2m to create single stemmed tree Crown lift to 5.2m over Highway
Sgl/38	(226872	Cypress	6.0m	24cm	Semi-mature	Single Stemmed Co-dominant Stems	Crown Reduction by - 40%
Sgl/39	(226876	Cypress	6.0m	24cm	Semi-mature	Single Stemmed Co-dominant Stems	Crown Reduction by - 40%
Sgl/40	(226880	Beech	7.0m	24cm	Young	Lean < than 20% Single Stemmed Co-dominant Stems Suppressed	Crown lift to 5.2m over Highway
Sgl/41	(226884	English Oak	15.0m	54cm	Semi-mature	Single Stemmed Co-dominant Stems Major Deadwood - BRANCHES/STEMS Over Extended Major Branching	Remove major deadwood Crown lift to 5.2m over Highway Reduce o/extended branches - limb over main road by up to 3m leave tree in good form
Sgl/42	(226888	English Oak	13.0m	41cm	Semi-mature	Single Stemmed Co-dominant Stems Major Deadwood - BRANCHES/STEMS	Remove major deadwood Crown lift to 5.2m over Highway
Sgl/43	(226892	English Oak	10.0m	42cm	Semi-mature	Lean > than 20% Single Stemmed Co-dominant Stems I mbalanced crown Major Deadwood - BRANCHES/STEMS Suppressed	Fell to ground level

Hurn Road - St Catherine's Way R/a ..(H) ...(contd)...

Tree Nur	mber	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/44	(226896	English Oak	13.0m	41cm	Semi-mature	Lean < than 20% Single Stemmed Co-dominant Stems I mbalanced crown Major Deadwood - BRANCHES/STEMS Suppressed	Remove major deadwood Crown lift to 5.2m over Highway
Sgl/45	(226900	English Oak	14.0m	39cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove epicormics - trunk/crown Remove major deadwood Crown lift to 5.2m over Highway
Sgl/47	(226908	Sycamore	9.0m	19cm	Young	Single Stemmed Co-dominant Stems I mbalanced crown Major Deadwood - BRANCHES/STEMS Suppressed	Fell to ground level Grind Stump & reinstate
Sgl/48	(226912	Monterey Cypres	3.0m	13cm	Young	Dead Single Stemmed Co-dominant Stems	Fell to ground level
SgI/49	(226916	Monterey Cypres	5.0m	13cm	Young	Dead Single Stemmed Co-dominant Stems	Fell to ground level
Sgl/50	(226920	Cypress	6.0m	24cm	Semi-mature	Single Stemmed Co-dominant Stems Tight Forks/Included Bark-MAIN FORK	Fell to ground level
Sgl/51	(226924	Cypress	6.0m	24cm	Semi-mature	Single Stemmed Co-dominant Stems Tight Forks/Included Bark-MAIN FORK Suppressed	Fell to ground level

Hurn Road - St Catherine's Way R/a ..(H) ...(contd)...

Tree Nur	mber	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/52	(226928	Cypress	6.0m	24cm	Semi-mature	Single Stemmed Co-dominant Stems Tight Forks/Included Bark-MAIN FORK	Fell to ground level
Sgl/54	(226936	English Oak	5.0m	22cm	Young	Single Stemmed Ivy/climbers Restricting Inspection	Ivy band @ base Crown lift to 5.2m over Highway
Sgl/55	(226940	English Oak	4.0m	15cm	Young	Single Stemmed I mbalanced crown I vy/climbers Restricting I nspection Suppressed	Fell to ground level
SgI/56	(226944	Silver Birch	5.0m	21cm	Young	Single Stemmed Ivy/climbers Restricting Inspection	I vy band @ base
Sgl/57	(226948	English Oak	14.0m	34cm	Semi-mature	Single Stemmed Ivy/climbers Restricting Inspection	Ivy band @ base Crown lift to 5.2m over Highway
Sgl/58	(226952	English Oak	9.0m	36cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Crown lift to 5.2m over Highway
Sgl/59	(226956	English Oak	9.0m	36cm	Semi-mature	Single Stemmed Imbalanced crown Major Deadwood - BRANCHES/STEMS Suppressed	Remove major deadwood Crown lift to 5.2m over Highway
SgI/60	(226960	English Oak	8.0m	30cm	Young	Single Stemmed Suppressed	Crown lift to 5.2m over Highway

Hurn Road - St Catherine's Way R/a ..(H) ...(contd)..

Tree Number	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/61 (226964	English Oak	8.0m	30cm	Young	Single Stemmed Suppressed	I vy band @ base Crown lift to 5.2m over Highway
Sgl/63 (226972	English Oak	11.Om	38cm	Semi-mature	Single Stemmed I mbalanced crown Major Deadwood - BRANCHES/STEMS Suppressed	Fell to ground level
Sgl/64 (226976	English Oak	16.0m	65cm	Semi-mature	Single Stemmed Co-dominant Stems Lvy/climbers Restricting Inspection Major Deadwood - BRANCHES/STEMS	I vy band @ base Crown lift to 5.2m over Highway
Sgl/65 (226980	English Oak	5.0m	22cm	Young	Single Stemmed Ivy/climbers Restricting Inspection	I vy band @ base Crown lift to 5.2m over Highway
SgI/66 (22698 ²	English Oak	13.0m	38cm	Semi-mature	Multi-Stemmed Ivy/climbers Restricting Inspection Major Deadwood - BRANCHES/STEMS	Remove epicormics - trunk/crown Remove major deadwood I vy band @ base Crown lift to 5.2m over Highway
SgI/68 (226992	Scot's pine	15.Om	60cm	Semi-mature	Single Stemmed Co-dominant Stems Tight Forks/Included Bark-MAIN FORK Ivy/climbers Restricting Inspection Major Deadwood - BRANCHES/STEMS Suppressed	Fell to ground level

Hurn Road - St Catherine's Way R/a ..(H) ...(contd)...

Tree Number	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/69 (22700 ²	Scot's pine	15.Om	60cm	Semi-mature	Single Stemmed Ivy/climbers Restricting Inspection Major Deadwood - BRANCHES/STEMS	I vy band @ base
Sgl/70 (227008	Cypress	8.0m	27cm	Semi-mature	Single Stemmed Co-dominant Stems Tight Forks/Included Bark-MAIN FORK	Fell to ground level
SgI/72 (227016	Sycamore	7.0m	19cm	Young	Single Stemmed Co-dominant Stems	Crown lift to 5.2m over Highway
Sgl/74 (22702 ⁴	Beech	5.0m	24cm	Young	Lean < than 20% Single Stemmed Co-dominant Stems Suppressed	Formative and corrective pruning - remove small co-dominent stem
SgI/79 (22704 ²	Scot's pine	10.0m	29cm	Semi-mature	Lean > than 20% Single Stemmed Suppressed	Fell to ground level
Sgl/81 (227052	Silver Birch	5.0m	19cm	Young	Lean > than 20% Multi-Stemmed	Fell to ground level
Sgl/82 (22705∂	English Oak	15.0m	38cm	Semi-mature	Single Stemmed Ivy/climbers Restricting Inspection Major Deadwood - BRANCHES/STEMS	Remove major deadwood I vy band @ base Crown lift to 5.2m over Highway

Tree work - Hurn Road Xchurch - 2013 - Highways - General Tree Report Date: 18/10/2012ge 18

Hurn Road - St Catherine's Way R/a ..(H) ...(contd)...

Tree Num	ber	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/83 ((227060	Monterey pine	12.0m	41cm	Semi-mature	Lean > than 20% Single Stemmed Co-dominant Stems I mbalanced crown Major Deadwood - BRANCHES/STEMS Suppressed Tight Forks/I ncluded Bark @ > 1.5m	Fell to ground level Grind Stump & reinstate
Sgl/84 ((227064	Scot's pine	12.0m	38cm	Semi-mature	Single Stemmed Suppressed	I vy band @ base
Sgl/85 ((227068	Scot's pine	12.0m	38cm	Semi-mature	Single Stemmed Suppressed	Fell to ground level Grind Stump & reinstate
Sgl/87 ((22707ℓ	Scot's pine	6.0m	18cm	Young	Single Stemmed Suppressed	Fell to ground level
Sgl/88 ((227080	Scot's pine	8.0m	18cm	Young	Lean > than 20% Single Stemmed Suppressed	Fell to ground level
Sgl/89 ((227084	Silver Birch	6.0m	19cm	Semi-mature	Single Stemmed I vy/climbers Restricting I nspection	I vy band @ base
Sgl/93 ((22710C	Scot's pine	10.0m	28cm	Semi-mature	Single Stemmed I mbalanced crown Suppressed	Fell to ground level
Sgl/94 ((227104	Scot's pine	10.0m	28cm	Semi-mature	Single Stemmed I mbalanced crown Hanging broken branch Suppressed	Remove hanging/broken branch

Date: 18/10/20 13 e 19

Hurn Road - St Catherine's Way R/a ..(H) ...(contd)...

6 Months - PLANNED ...(contd)..

Tree Nu	ımber	Common name	Height	Trunk	Age Class	Condition	Recommendations
SgI/95	(227108	Scot's pine	6.0m	18cm	Young	Single Stemmed Ivy/climbers Restricting Inspection	I vy band @ base
Sgl/96	(227112	Scot's pine	6.0m	18cm	Young	Single Stemmed Ivy/climbers Restricting Inspection	I vy band @ base
Sgl/97	(227116	Scot's pine	7.Om	18cm	Young	Multi-Stemmed I vy/climbers Restricting I nspection Tight Forks/I ncluded Bark @ < 1.5m	Fell to ground level
Sgl/98	(22712C	Monterey pine	13.0m	43cm	Semi-mature	Lean > than 20% Single Stemmed Co-dominant Stems I mbalanced crown Major Deadwood - BRANCHES/STEMS Suppressed Tight Forks/I ncluded Bark @ > 1.5m	Remove major deadwood Crown lift to 5.2m over Highway

Sub-total: 77 trees

28 days -MED TERM 2b

Tree Nu	mber	Common name	Height	Trunk	Age Class	Condition	Recommendations
SgI/75	(227028	Myrobalan plum	4.0m	23cm	Young	Lean < than 20% Single Stemmed Co-dominant Stems Suppressed	Crown lift to 5.2m over Highway

Hurn Road - St Catherine's Way R/a .. (H) ...(contd)..

28 days -MED TERM 2b ...(contd)..

Tree Number Trunk Condition Common name Height Age Class Recommendations

(22704(Scot's pine Single Stemmed Remove hanging/broken branch 58cm Sql/78 12.0m Semi-mature

Co-dominant Stems Hanging broken branch Major Deadwood -**BRANCHES/STEMS**

Sub-total: 2 trees

7 days-SHORT TERM 2a

Age Class Condition Tree Number Common name Height Trunk Recommendations

SgI/20 12.0m 43cm Further inspection required (22674 English Oak Semi-mature Bat potential - high Multi-Stemmed Consult Ecologist

Co-dominant Stems Major Deadwood -BRANCHES/STEMS Cavities - BATS -

Remove major deadwood

road byup to 3-4m

Crown lift to 5.2m over Highway

Reduce o/extended branches -

reduce split limb over service

BRANCHES/STEMS Splits/Cracks - MAIN **BRANCHES/STEMS**

Sub-total: 1 trees

> Total: 80 trees

River Way St Catherines Way End Xch (H)

28 days -MED TERM 2b

Condition Tree Number Common name Height Trunk Age Class Recommendations

River Way St Catherines Way End Xch (H) ...(contd)..

28 days -MED TERM 2b ...(contd)...

Tree Nu	umber	Common name	Height	Trunk	Age Class	Condition	Recommendations
SgI/7	(222424	English Oak	15.Om	55cm	Mature	Single Stemmed Co-dominant Stems Forks > 1.5m Minor Deadwood-BRANCHES/STEMS Old pruning wounds-callousing well Multiple Pruning Wounds - TRUNK	Remove major deadwood
SgI/8	(222428	English Oak	16.0m	61cm	Semi-mature	Single Stemmed Forks > 1.5m Minor Deadwood-BRANCHES/STEMS Multiple Pruning Wounds - TRUNK	Reduce o/extended branches - by 2-3m large limb above footpath/road
Sgl/11	(222440	English Oak	15.Om	55cm	Semi-mature	Single Stemmed Forks > 1.5m Major Deadwood - BRANCHES/STEMS Minor Deadwood-BRANCHES/STEMS	Remove major deadwood Crown Reduction by - 2m to suitable point leaving in good form
Sgl/12	(222444	'Vacant tree pit'	0.0m	Ocm		None recorded	Plant replacement tree - clear norway maples over tree pit

Sub-total: 4 trees

> Total: 4 trees

Single Stemmed Co-dominant Stems Formative and corrective pruning Remove stake

Date: 18/10/2013e 22

St Catherines Way River Way St.cath..(H)

(224276 Norway Maple

2.0m

8cm

Young

SgI/5

6 Months -	PLANNED
------------	---------

Tree Number	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/8 (226164)	Scot's pine	15.0m	38cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove major deadwood
Sgl/9 (226168)	Scot's pine	13.0m	38cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove major deadwood Reduce heavy branch weight by - 2m -limb over footpath
Sgl/10 (226172	Scot's pine	15.0m	31cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove major deadwood
Sgl/11 (226176)	Scot's pine	13.0m	33cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove major deadwood
Sgl/13 (226184	English Oak	14.0m	42cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS Suppressed	Remove major deadwood
				Sub-tota	l: 5 trees	
28 days -MED TE	RM 2b					
Tree Number	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/4 (224268	Red Oak	6.0m	37cm	Young	Single Stemmed Co-dominant Stems Forks > 1.5m	Crown clean Remove epicormics - trunk/crown Crown lift to 2.3 m over Footpath

St Catherines Way River Way St.cath..(H) ...(contd)..

28 days -MED TERM 2b ...(contd)...

Tree Number	Common name	Height	Trunk	Age Class	Condition	Recommendations
Sgl/6 (224472	Red Oak	11.Om	37cm	Semi-mature	Single Stemmed Co-dominant Stems Forks > 1.5m Major Deadwood - BRANCHES/STEMS	Crown clean Crown lift to 2.3 m over Footpath
SgI/7 (224648	English Oak	15.0m	40cm	Semi-mature	Single Stemmed Major Deadwood - BRANCHES/STEMS	Remove major deadwood
Sgl/12 (226180	English Oak	11.0m	40cm	Semi-mature	Single Stemmed I mbalanced crown Major Deadwood - BRANCHES/STEMS Suppressed	Remove major deadwood
SgI/14 (226188	English Oak	13.0m	44cm	Semi-mature	Multi-Stemmed Major Deadwood - BRANCHES/STEMS Suppressed	Remove major deadwood Reduce o/extended branches - dog legged limb over main road with cavity by 2m

Sub-total: 6 trees

Total: 11 trees

Notes: -

Overall total: 134 trees

Highways - General Tree Report - Tree work - Hurn Road Xchurch - 2013









